

COLLINS GENERAL AVIATION DIVISION
COMPONENT MAINTENANCE MANUAL with IPL
AHC-85D/85E, PART NO 622-7386-001

changeable with the items in the older style shipping containers. Refer to figure 701 for a drawing of the revised shipping container. This exploded view also shows the packing order.

Collins approved shipping container items are available for purchase through our Service Parts Organization, telephone number (800) 327-0854 in the continental US and (407) 768-7234 internationally.

COLLINS APPROVED
AHC-85D/85E SHIPPING CONTAINER

| <u>ITEM</u> | <u>COLLINS PART NO</u> | <u>QTY</u> | <u>*LIST PRICE</u> |
|---------------------|----------------------------|------------|------------------------|
| Corrugated box | 169-5078-000 | 1 | \$14.71 |
| End cap, foam | 169-5076-000 | 2 | \$18.66 |
| Top pad | 169-5077-000 | 1 | \$22.13 |
| Inner carton | 169-5074-000 | 1 | \$ 8.79 |
| Bottom insert, foam | 169-5075-001 | 1 | \$20.70 |
| Top insert, foam | 169-5075-002 | 1 | \$20.70 |

*List prices are subject to change without notice.

CAUTION: OBSERVE THE FOLLOWING GUIDELINES TO AVOID DAMAGE AND EXPENSIVE REPAIR BILLS:

DO TRANSPORT THE AHC IN THE NEW APPROVED SHIPPING CONTAINER.
DO NOT MOVE, TRANSPORT OR SHIP AN AHC UNLESS IT IS IN THE APPROVED SHIPPING OR INNER CARTON, AS CONDITIONS WARRANT.

DO HANDLE THE AHC GENTLY.
DO NOT PLOP IT DOWN ON THE RAMP OR THE SHIPPING TABLE. IF ONE END

OF THE AHC IS DROPPED FROM A HEIGHT OF JUST 19 MM (3/4 IN), THAT IS EQUIVALENT TO A 20-G IMPACT (APPROXIMATELY).

DO STORE THE AHC IN THE NEW APPROVED CONTAINER.
DO NOT STORE AN UNPROTECTED AHC ON A HARD SHELF.